

hohner

Esquema de ligação. Conector 25 pinos DB25 -Macho.

XXXX-XXXX-XXXX	XXXX-XXXX-XXXX	XXXX-XXXX-XXXX
Pino 1 = - 0 Volts	Pino 1 = - 0 Volts	Pino 1 = - 0 Volts
Pino 2 = + 5 a 28 Volts	Pino 2 = + 5 a 28 Volts	Pino 2 = + 5 a 28 Volts
Pino 3 = Canal A	Pino 3 = Canal A	Pino 3 = Canal A
Pino 4 = N/C	Pino 4 = N/C	Pino 4 = N/C
Pino 5 = N/C	Pino 5 = N/C	Pino 5 = N/C
Pino 6 = N/C	Pino 6 = N/C	Pino 6 = N/C
Pino 7 = N/C	Pino 7 = N/C	Pino 7 = N/C
Pino 8 = N/C	Pino 8 = N/C	Pino 8 = N/C
Pino 9 = N/C	Pino 9 = N/C	Pino 9 = N/C
Pino10 = N/C	Pino10 = N/C	Pino10 = N/C
Pino11 = Malha	Pino11 = Malha	Pino11 = Malha
Pino12 = N/C	Pino12 = N/C	Pino12 = N/C
Pino13 = N/C	Pino13 = N/C	Pino13 = N/C
Pino14 = N/C	Pino14 = N/C	Pino14 = N/C
Pino15 = N/C	Pino15 = N/C	Pino15 = N/C
Pino16 = N/C	Pino16 = N/C	Pino16 = N/C
Pino17 = N/C	Pino17 = N/C	Pino17 = N/C
Pino18 = N/C	Pino18 = N/C	Pino18 = N/C
Pino19 = N/C	Pino19 = N/C	Pino19 = N/C
Pino20 = N/C	Pino20 = N/C	Pino20 = N/C
Pino21 = N/C	Pino21 = N/C	Pino21 = N/C
Pino22 = N/C	Pino22 = N/C	Pino22 = N/C
Pino23 = N/C	Pino23 = N/C	Pino23 = N/C
Pino24 = N/C	Pino24 = N/C	Pino24 = N/C
Pino25 = N/C	Pino25 = N/C	Pino25 = N/C